

Southeast District Office
411 W. Fourteenth
Chanute, KS 66720-2894



phone: 620-431-1000
fax: 620-431-4406
www.ksdot.org

Richard Carlson, Secretary

Sam Brownback, Governor

FOR IMMEDIATE RELEASE

July 19, 2017

Contact: Priscilla Petersen, (620) 902-6433; priscilla.petersen@ks.gov

Concrete repairs next week underneath I-35 at Williamsburg

Monday, July 24, the Kansas Department of Transportation (KDOT) expects to begin patching the deteriorated concrete pavement on the section of John Brown Road that runs underneath I-35 at exit 170, Williamsburg.

Flaggers will direct one-lane traffic through the work zone, with brief delays expected. The John Brown Road concrete repairs are included in the multi-county I-35 concrete patching project that started in March. Realm Construction, Inc., of Blue Springs, Mo., is the project contractor.

For more information contact Troy Howard, construction engineer at the Kansas Department of Transportation (KDOT) office at Garnett, (785) 448-5446, or Priscilla Petersen at the Chanute KDOT office, (620) 902-6433.

#####

This information can be made available in alternative accessible formats upon request.

For information about obtaining an alternative format, contact the Bureau of Transportation Information, 700 SW Harrison St., 2nd FL West, Topeka, KS 66603-3754 or phone 785-296-3585 (Voice)/Hearing Impaired – 711.

Click below to connect to KDOT's Social Networks:



YouTube

flickr