

South Central District Office
500 N. Hendricks
Hutchinson, KS 67504-0769



phone: 620-663-3361
fax: 620-663-1804
www.ksdot.org

Julie Lorenz, Secretary

Laura Kelly, Governor

IMMEDIATE RELEASE

March 4, 2020

For more information: Tim Potter

620-860-7389; mobile: 620-727-2278; Tim.Potter@ks.gov

Traffic flow change at U.S. 50/281 roundabout work zone

A change occurred today (Wednesday, March 4) in the traffic configuration at the U.S. 50/281 roundabout being built near St. John in Stafford County.

Traffic has now been rerouted from a four-way stop and temporary asphalt detour at the construction site. Motorists will now drive on a permanent concrete diamond-shaped outer road for the roundabout.

Motorists will have to stop before entering the diamond.

The roundabout, which is expected to be completed around mid-June, will have an inner road for regular traffic and the outer diamond-shaped road for oversize loads.

The project is being overseen by the Kansas Department of Transportation.

####

This information can be made available in alternative accessible formats upon request.

For information about obtaining an alternative format, contact the KDOT Division of Communications,
700 SW Harrison St., 2nd Fl West, Topeka, KS 66603-3754 or phone 785-296-3585 (Voice)/Hearing Impaired – 711.

Click below to connect to KDOT's Social Networks:



